Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Development of Slab Drainfrom 15th Cross to SWD Drain in Side J.P.Park in Ward No.17 in RRN Zone
2	Administration Approval & Date	AC/RRN/AS/167/12-13 Dtd 23-05-2012 by AC (RRN)
3	Technical Sanction Estimate No. & Date	EE/RRNZ/TS/81/12-13 dtd:06-06-2012 by EE (RRN)
4	Estimate Amount	Rs.19.95/- Lakhs
5	Job Code No.	017-12-000085
6	P-Code	P-2570
7	Agreement No & date	EE(P)/RRN/AG No./124/2012-13 Dtd.12-10-2012
8	Work order Number & Date	EE/Proj/RRN/W.O/124/2012-13 Dtd.12-10-2012
9	Contract Amount as per Agreement	20,84,812/-
10	Bill Amount	Rs.20,73,556/-
11	B.R. No. & Date	161/2012-13 dt.29-08-2013
12	Agency	K.Sudhakar
13	M.B. Number & Page No. of Measurement recordes	1389/ Pages 138815 to 138823
14	Date of Inspection	6/7/2015
15	Enclusures	1) Extract of MB No.1389 Page No.138822/2 2) 4 Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site along with the concerned officials. The measurements were checked by me and it is found to be satisfactory

6/7/2015

EE (P) RR Nagara

(R.Sathyanarayana)
Inspection Report officer,

Location Sketch

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8



28/12/15

29/8/13

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಪಾಲಿಕೆ ವಿಭಾಗ ಕಛೇರಿ ಪೂರ್ವ ವಿಭಾಗ-02
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Serial No.....
Name of wor
Name of Cor
Date of com

Date	Ful
1	

6/7/2015
R. Sathyanarayan
Inspection officer